U.S. Department of Transportation

United States Coast Guard

8TH DISTRICT LOCAL NOTICE TO MARINERS

GULF OF MEXICO

Econfina River, FL to the Rio Grand, TX
LIGHT LIST VOLUME IV
WEEKLY SUPPLEMENT

** Electronic Bulletin Board Service: (703) 313-5910 **
300 to 28.8 bps, 8 data bits, no parity, 1 stop bit

** NIS watchstander, 24 hours a day at (703) 313-5900 **

INTERNET ADDRESS
HTTP://www.navcen.uscg.mil
OR
FTP://ftp.navcen.uscg.mil

NOTICE NUMBER 22-97

May 27, 1997

Issued by: Commander, Eighth Coast Guard District (oan)

Hale Boggs Federal Building, Room 1230 501 Magazine Street, New Orleans, LA 70130-3396

Telephone (504) 589-6277 (Office hours 6:30 a.m. - 4:00 p.m., M-F) (504) 589-6225 (Nights, Holidays, and Weekends)

Information of immediate concern to the mariner, and promulgated by the following broadcasts has been incorporated into this notice when still significant:

- CCGD8 (D8) BNM 0120-97 (D8) to 0126-97 (D8)
- CCGD8 (OB) BNM 0075-97 (OB) to 0079-97 (OB)
- GROUP MOBILE (MO) BNM 0383-97 (MO) to 0400-97 (MO)
- GROUP NEW ORLEANS (NO) BNM 0605-97 (NO) to 0621-97 (NO)
- GROUP GALVESTON (GA) BNM 0553-97 (GA) to 0571-97 (GA)
- GROUP CORPUS CHRISTI (CC)
 BNM 0251-97 (CC)
 to 0262-97 (CC)

Notes: (1) The Local Notice to Mariners consists of a Monthly Edition and Weekly Supplements. The monthly edition should be maintained

as a reference. Recurring information is published once a month.

(2) The current monthly edition is Notice Number 19-97.

LIGHT LIST REFERENCE: COMDTPUB P16502.4, Vol. IV, 1996 Edition.

(1)

SPECIAL NOTICES

OIL WELL STRUCTURES IN THE GULF OF MEXICO

Caution should be exercised when navigating in the Gulf of Mexico, in order to avoid collision with oil well structures and their associated mooring piles,

anchor and mooring buoys, etc. In general, oil well structures can be identified at night by the display of one or more quick flashing white or red lights.

However, ships can expect to encounter unlighted structures as well. Structures may be equipped with a fog signal consisting of a horn sounding one 2-

second blast every 20 seconds. Submerged wells may be marked by lighted or unlighted buoys.

Shipping safety fairways have been established through the concentration of oil wells in the Gulf of Mexico. Mariners are encouraged to use these

fairways and should avoid anchoring within a safety fairway. Certain areas adjacent to shipping safety fairways have been charted as fairway anchorages.

TIMELY REPORTING OF BRIDGE ALLISIONS TO THE COAST GUARD

All mariners are reminded of the importance of immediately reporting bridge collisions or rubbings of bridge support structures. The safety of the structure,

the people, and commerce who rely on the bridge is dependent upon timely notification to the proper authorities. Any collision with a bridge structure

should be immediately reported to the Coast Guard by any means available. The Coast Guard will in turn notify the proper federal, state, local, and/or

bridge authorities in order to initiate a timely response. Any delay in reporting a collision or rubbing could potentially jeopardize the safety and lives of

innocent people.

SUBMERGED OFFSHORE PIPELINES

Throughout the Gulf of Mexico, numerous submerged pipelines exist in the navigable waters used by both large and small vessels. These submerged

pipelines carry natural gas under high pressure and petroleum products. In inshore areas, these submerged pipelines are usually buried beneath the

seabed, but in offshore areas the pipeline may lie on the ocean floor. The locations of numerous submerged pipelines are not known. A selection of

submerged pipelines is shown on National Ocean Service (NOS) nautical charts from information which has been reported to NOS. However, additional

uncharted submerged pipelines may exist within the area of the chart.

Several incidents have occurred where vessels have struck these submerged pipelines leading to loss of life and property due to the explosion and fire

resulting from damage to the pipelines. Investigations of these incidents indicate many mariners believe that because the submerged pipelines were

buried at installation, they remain buried and do not pose a danger to vessels or operators. Mariners should be aware that winter storms, hurricanes, and

the placement of man-made structures such as jetties, can lead to erosion and subsidence and the removal of the sediment covering the submerged

pipelines.

In view of the serious consequences resulting from damage to submerged pipelines, vessel operators operating in water depths at or near the vessel's

draft or when operating bottom dragging equipment, should take special care near areas where these submerged pipelines may exist or have been

reported to exist.

Operators of offshore gas or hazardous liquid pipeline facilities are now required to mark pipelines which are found to be buried less than 12 inches below

the mudline with yellow lighted buoys displaying flashing yellow lights (flashing less than 30 times per minute). These buoys are to be placed on the

exposed segments of pipelines at intervals of not more than 500 yards apart. However, if the exposed segment of pipeline is less than 200 yards in

length, only one lighted buoy will be placed at the center of the segment.

Vessel operators fouling a submerged pipeline should attempt to clear the pipeline without excessive force. Anchors or gear that cannot be cleared

should be released without damaging the pipeline. Exposed pipelines are a hazard to navigation. Mariners discovering an exposed pipeline should report

the location immediately to the U.S. Coast Guard.

(2)

DISCREPANCIES

| | | | BNM | LNM | | | |
|----------|----------------------------|---------------|---------|---------|---------|-------|-------|
| 01250.00 | FREEPORT ENT LWB F | P RAC IN | OP | 11300 | 0556-97 | 7 GA | 22/97 |
| 03310.00 | ST ANDREW BAY LT 28 | LT EXT | 11389 | - | 22/97 | | |
| 05280.00 | MOBILE CH LT 51 L | _T IMCH | 11376 | 0393-97 | 7 MO | 22/97 | |
| 07390.00 | BAYOU CASOTTE CH L | T 4 TRLB | 11374 | 0395-97 | 7 MO | 22/97 | |
| 07815.00 | BILOXI CH LT 8 T | ΓRLB 11372 | - | 22/97 | | | |
| 07825.00 | BILOXI CH LT 10 T | ΓRLB 11372 | - | 22/97 | | | |
| 07830.00 | BILOXI CH LT 12 T | ΓRLB 11372 | 0610-97 | 7 NO | 22/97 | | |
| 08575.00 | GULFPORT SHIP CH LT | 36 LT EXT | 11372 | - | 22/97 | | |
| 15445.00 | BAYOU RIGAUD LT 7 N | ∕IISSING | 11352 | 0619-97 | 7 NO | 22/97 | |
| 17090.00 | LAKE BOUDREAUX LT 1 | 19 LT EXT | 11352 | 0615-97 | 7 NO | 22/97 | |
| 18285.00 | AVOCA IS C/O CH B 1 T | ΓRUB 11351 | - | 22/97 | | | |
| 18355.00 | ATCHAFALAYA RIV LT 2 | 23 TRUB | 11351 | - | 22/97 | | |
| 22930.00 | HSC LT 36 TRLB 1 | 11324 0560-97 | ′ GA | 22/97 | | | |
| 23000.00 | HSC LT 47 TRLB 1 | 11326 0566-97 | ′ GA | 22/97 | | | |
| 23160.00 | HSC LT 66 MISSING | 3 11326 | 0569-97 | 7 GA | 22/97 | | |
| 23300.00 | HSC B 76A MISSING | G 11326 | 0568-97 | 7 GA | 22/97 | | |
| 24450.00 | HSC LT 133 MISSING | G 11326 | 0567-97 | 7 GA | 22/97 | | |
| 24775.00 | TEXAS CITY CH LT 12 N | ∕IISSING | 11324 | 0571-97 | 7 GA | 22/97 | |
| 29630.00 | EAST BAY LT 43 T | TRLB 11390 | 0396-97 | 7 MO | 22/97 | | |
| 37620.00 | ARANSAS BAY A/R B 77 | 7 OFF ST | Α | 11314 | 0261-97 | 7 CC | 22/97 |
| | | | | | | | |

PRIVATE AID DISCREPANCIES

| LLNR NAME | OF AID STATUS | CHARTS | BNM | LNM | | | |
|-----------|--------------------|--------------|--------|-------|-------|------------|-------|
| 00171.50 | SCIENCE INTL. INST | MENT BUOY E1 | MISSIN | ٧G | 11360 | 0121-97 D8 | 22/97 |
| 37710.00 | LYDIA ANN CH LT | LT EXT 11307 | - | 22/97 | | | |

DISCREPANCIES CORRECTED

| DIOONE! /! | TOILS SOMMESTED | | | | | | | |
|-------------------|-------------------------|---------------------|----------|-----------|---------|--------------|--------|--------|
| | | | | LNM | | | | |
| 05150.00 | | | 11376 | | | 21/97 | | |
| 05170.00 | | | 11376 | | 22/97 | | | |
| 06890.00 | HORN IS PASS LB 10 RELI | | 11373 | | | 21/97 | | _ |
| 09500.00 | ALLIGATOR PT LT WAT | | | | | | | 22/97 |
| 09540.00 | RIGOLETS-NEW ORLEANS | JCT DBN E | 3 | WATCH | HING PR | ROPERL | Y | 11371 |
| - | 22/97 | | | | | | | |
| 10145.00 | TCHEFUNCTA RIV RR LT | | | | | | 22/97 | |
| 12375.00 | BAPTISTE COLLETTE BAYO | OULI5 | REBUIL | .I/REC | JVEREL |) | 11363 | - |
| 10/97 | DADTIOTE 0011 ETTE DAV | | | T/D = 0.4 | | _ | | |
| 12440.00 | BAPTISTE COLLETTE BAYO | DU LI 18 | REBUIL | .I/REC | JVEREL |) | 11363 | 0559- |
| 97 NO 20/97 | DADTIOTE COLLETTE DAVI | N.I.T.05 | DED | T/DE04 | _D | | 44004 | 0.400 |
| 12460.00 | BAPTISTE COLLETTE BAYO | O L 1 25 | KEBUIL | .I/RECC | JVEREL |) | 11361 | 0438- |
| 97 NO 15/97 | LIEAD OF BASSES ICTLE | DELIGII | TED | 44004 | | 22/07 | | |
| 12900.00 | HEAD OF PASSES JCT LT | | | | | 22/97 | | |
| 12980.00 | CUBITS GAP LT 4 RELI- | | 11361 | | 22/97 | 11370 | 0005.0 | 7 NO |
| 13795.00 03/97 | HUET P LONG BRIDGE APP | ВО | KESEI | ON 517 | ATION | 11370 | 0025-9 | / NO |
| 14950.00 | TIGER PASS LT 4 REBU | JILT/RECO | \/EDED | ١ | 11361 | | 18/97 | |
| 14960.00 | | JILT/RECO | | | | 0425-97 | | 16/97 |
| 15020.00 | | JILT/RECO | | | | 0425-97 | | 17/97 |
| 15030.00 | | JILT/RECO | | | 11361 | | 19/97 | 17/97 |
| 15035.00 | | JILT/RECO | | | | - 0251-97 | | 11/97 |
| 15060.00 | | JILT/RECO | | | 11361 | | 19/97 | 11/31 |
| 15115.00 | | JILT/RECO | | | 11361 | | 16/97 | |
| | OF AID STATUS CHAI | | | , LNM | 11301 | - | 10/97 | |
| 15130.00 | | JILT/RECO | | | 11361 | 0378-97 | 7 NO | 15/97 |
| 15165.00 | TIGER PASS DBN 48 REBI | | | | | 0250-97 | | 11/97 |
| 15380.00 | | T ON STA | | | 0604-97 | | 21/97 | 1 1/57 |
| 17090.00 | LAKE BOUDREAUX LT 19 | | | | 0601-97 | | 21/97 | |
| 19490.00 | SW PASS VERMILION BAY | | RELIGH | | 11345 | | 22/97 | |
| 20520.00 | CALCASIEU CH LB 19 RELI | | 11344 | | 21/97 | | 22/51 | |
| 21315.00 | SABINE BANK CH LB 1 | RELIGH | | 11332 | | 22/97 | | |
| 22610.00 | GALVESTON BAY ENT CH | | | | | 0559-97 | 7 GA | 22/97 |
| 22888.00 | HSC LT 28 WATCHING | | | | 0528-97 | | 20/97 | 22/01 |
| 22895.00 | HSC LT 30 RELIGHTED | 11324 | | 22/97 | 0020 0 | 0, (| 20,01 | |
| 23050.00 | UPPER GALVESTON BAY IN | | | RELIGH | HTED | 11326 | _ | 21/97 |
| 23185.00 | HSC LT 71 RELIGHTED | 11326 | | | 21/97 | | | , |
| 23290.00 | BAYPORT SHIP CH LT 8 | | | | | 11327 | 0545-9 | 7 GA |
| 21/97 | | | | | - | | | |
| 23330.00 | HSC LT 85 RELIGHTED | 11326 | 0561-97 | ' GA | 22/97 | | | |
| 23530.00 | HSC B 93 RESET ON S | TATION | 11326 | - | 22/97 | | | |
| 23535.00 | UPPER MORGANS PT INBC | | | | | 11328 | 0558-9 | 7 GA |
| 22/97 | | J. 12 . 11 _ | • | | | | | . • . |
| 23565.00 | HSC B 97 WATCHING | PROPERLY | ′ | 11326 | 0546-97 | 7 GA | 21/97 | |
| 24995.00 | DICKINSON BAYOU CH DBN | | | | | | | - |
| 21/97 | | | | - | | | | |
| 27420.00 | CORPUS CHRISTI CH LT 13 | REBUIL [®] | T/RECC | VERE |) | 11308 | 0250-9 | 7 CC |
| 21/97 | | | | | | | | |
| 27425.00 | CORPUS CHRISTI CH LT 14 | REBUIL [®] | T/RECC | VERE |) | 11308 | - | 22/97 |
| 27450.00 | CORPUS CHRISTI CH LT 25 | RELIGH | TED | 11308 | 0607-96 | S CC | 50/96 | |
| | | | | | | | | |

| 28015.00 | PORT MANSFIELD CH DBN 12 | RE | EBUILT/RECO | OVERED | • | 11306 | 0212- |
|-------------|----------------------------|------------|-------------|------------------|--------|-------|-------|
| 97 CC 18/97 | | | | | | | |
| 34278.00 | BOLIVAR PENINSULA LT 24 | RELIGHTE | ED 11324 | - 22 | 2/97 | | |
| 37765.00 | CC-BAFFIN BAY LT 17 RELIGH | HTED 11 | 308 - | 22/97 | | | |
| 37790.00 | CC-BAFFIN BAY LT 25 WATCH | HING PROF | PERLY | 11309 - | 2 | 22/97 | |
| 37960.00 | CC-BAFFIN BAY B 45 RESET | ON STATI | ON 11308 | - 22 | 2/97 | | |
| 38560.00 | CC-BAFFIN BAY LT 137 | RELIGHTE | ED 11308 | - 2 | 1/97 | | |
| 39010.00 | BAFFIN BAY L/C DBN 12 | REBUILT/F | REMAINS | 11308 - | • | 19/97 | |
| 39035.00 | BAFFIN BAY L/C DBN 20 | REBUILT/F | RECOVERED |) 1 [·] | 1308 - | | 19/97 |
| 39620.00 | LAND CUT-ARROYO COLORA | DO LT 118 | REBUIL | T/RECOV | /ERED | | 11306 |
| 0228-9 | 7 CC 19/97 | | | | | | |
| 39785.00 | LAND CUT-ARROYO COLORA | DO B 161A | A RESET | ON STAT | TION ' | 11306 | 0241- |
| 97 CC 21/97 | | | | | | | |
| 39825.00 | LAND CUT-ARROYO COLORA | .DO DBN 17 | 75 REBUIL | .T/RECOV | /ERED | | 11303 |
| 0239-9 | | | | | | | |
| 39875.00 | LAND CUT-ARROYO COLORA | DO LT 187 | ' REBUIL | .T/RECOV | /ERED | | 11303 |
| 0240-9 | 7 CC 21/97 | | | | | | |
| 39985.00 | ARROYO COLORADO C/O CH | N ENT B 3 | BN RESET | ON STAT | TION 1 | 11303 | 0234- |
| 97 CC 20/97 | | | | | | | |
| 40170.00 | HARLINGEN-PORT ISABEL LT | | ELIGHTED | | 248-97 | CC | 21/97 |
| 40230.00 | HARLINGEN-PORT ISABEL LT | | ELIGHTED | 11303 - | 2 | 21/97 | |
| 40270.00 | HARLINGEN-PORT ISABEL LT | 57 RE | ELIGHTED | 11303 - | 2 | 21/97 | |
| | | | | | | | |

44000 0040

PRIVATE AID DISCREPANCIES CORRECTED

DODE MANORIELD OU DON 40

LLNR NAME OF AID STATUS CHARTS BNM LNM

None

00045 00

PRIVATE AID PLATFORM DISCREPANCIES

PLATFORM DISCREPANCY POSITION BNM LNM

SANTE FE-114-2 LT EXT 29²08'14.0"N 92²22'37.0"W - 22/97

PRIVATE AID PLATFORM DISCREPANCIES CORRECTED

PLATFORM STATUS POSITION BNM LNM

CHEVRON-153-2 RELIGHTED 29211'25.0"N 91236'26.0"W 0387-97 NO 16/97

(3)

TEMPORARY CHANGES

LLNR NAME OF AID STATUS CHARTS BNM LNM

None

TEMPORARY CHANGES CORRECTED

LLNR NAME OF AID STATUS CHARTS BNM LNM

None

(4)

CHART CORRECTIONS

1115A 37 ed., 12/07/96 LAST LNM 21/97 NAD 83(CGD8) 22/97

MS - CAPE ST. GEORGE TO MISSISSIPPI PASSES - MINERAL LEASE CHART

Add Platform: "CH-MP-120-1-CE" 29²27'52.0"N 88²41'09.0"W Platform: "ZI-MP-92-12" 29²36'59.0"N 88²51'56.0"W

1116A 60 ed., 03/22/97 LAST LNM 21/97 NAD 83(CGD8) 22/97

GULF COAST - MISSISSIPPI RIVER TO GALVESTON

Delete Platform: "NFE-WD-35-2" 2920932.0"N 8924756.0"W

Add Platform: "ZI-GI-82-A" 28243'17.0"N 89257'55.0"W

1117A 33 ed., 11/19/94 LAST LNM 21/97 NAD 83(CGD8) 22/97

TX - GULF COAST GALVESTON TO RIO GRAND

Add Position circle with legend: "Well (covered 18fms)" 28216'41.0"N 95229'17.0"W

11300 33 ed., 11/19/94 LAST LNM 21/97 NAD 83(CGD8) 22/97

TX - GULF COAST GALVESTON TO RIO GRAND

Add Position circle with legend: "Well (covered 18fms)" 28216'41.0"N 95229'17.0"W

11307 34 ed., 07/27/96 LAST LNM 19/97 NAD 83(CGD8) 22/97

TX - ARANSAS BAY TO BAFFIN BAY

Change Platform: "BHP-MU-746L-1" to "FI-MU-746L-1" 27²45'24.0"N 96²58'55.0"W (Supersedes LNM 19/97)

11323 54 ed., 08/06/94 LAST LNM 21/97 NAD 83(CGD8) 22/97

TX - APPROACHES TO GALVESTON BAY

Delete "Visible Wreck Symbol (PA)" (CGD8 073-97) 29221'00.0"N 94242'00.0"W

11324 29 ed., 02/22/97 LAST LNM 20/97 NAD 83(CGD8) 22/97

TX - GALVESTON BAY ENTRANCE

Delete "Visible Wreck Symbol (PA)" (CGD8 073-97) 29221'00.0"N 94242'00.0"W

11326 26 ed., 01/01/94 LAST LNM 21/97 NAD 83(CGD8) 22/97

TX - FOLIO SMALL - CRAFT CHART GALVESTON BAY

Change Marina on the Lake Daybeacon "1" to

Marina Del Sol Light "1", Fl G 4s, 16ft, (Priv maint) 29²33'24.0"N 95²02'57.0"W

Delete "Visible Wreck Symbol (PA)" (CGD8 073-97) 29²21'00.0"N 94²42'00.0"W

11330 11 ed., 09/30/95 LAST LNM 21/97 NAD 83(CGD8) 22/97

TX - MERMEMTAU RIVER TO FREEPORT

Add Position circle with legend: "Well (covered 133ft)" 28216'41.0"N 95229'17.0"W

11340 60 ed., 03/22/97 LAST LNM 21/97 NAD 83(CGD8) 22/97

GULF COAST - MISSISSIPPI RIVER TO GALVESTON

Delete Platform: "NFE-WD-35-2" 2920932.0"N 8924756.0"W

Platform: "UPRC-WC-420-A" (Union Pacific-105-1) 28²41'57.0"N 93²36'05.0"W

Add Platform: "ZI-GI-82-A" 28243'17.0"N 89257'55.0"W

11349 36 ed., 06/22/96 LAST LNM 20/97 NAD 83(CGD8) 22/97

(Temp) LA - VERMILION BAY AND APPROACHES

Add Freshwater Bayou Lighted Obstruction Buoy "WR1", Q G, green (CGD8 089-97)

29232'24.0"N 92218'28.0"W

- 11349 36 ed., 06/22/96 LAST LNM 20/97 NAD 83(CGD8) 22/97 LA - VERMILION BAY AND APPROACHES Symbol: "Submerged Obstruction (PA)" and legend: "(covered 2ft)" (CGD8 089-97) 29²32'24.0"N 92²18'28.0"W
- 11350 21 ed., 04/27/96 LAST LNM 07/97 NAD 83(CGD8) 22/97 (Temp) LA - ICW - WAX LAKE OUTLET TO FORKED ISLAND INCLUDING BAYOU TECHE, VERMILLION RIVER AND FRESHWATER BAYOU

Freshwater Bayou Lighted Obstruction Buoy "WR1", Q G, green 29232'24.0"N 92218'28.0"W

- 11350 21 ed., 04/27/96 LAST LNM 07/97 NAD 83(CGD8) 22/97 LA - ICW - WAX LAKE OUTLET TO FORKED ISLAND INCLUDING BAYOU TECHE, VERMILLION RIVER AND FRESHWATER BAYOU Symbol: "Submerged Obstruction (PA)" and legend: "(covered 2ft)" 29²32'24.0"N 92218'28.0"W
- 11352 33 ed., 11/04/95 LAST LNM 21/97 NAD 83 (CGD8) 22/97 LA - NEW ORLEANS TO CALCASIEU RIVER EAST Delete Platform: "NFE-WD-35-2" 29209'32.0"N 89247'56.0"W
- 11357 31 ed., 03/16/96 LAST LNM 21/97 NAD 83(CGD8) 22/97 LA - TIMBALIER AND TERREBONNE BAYS Relocate California Canal Entrance Light "C" (29203'40.1"N 90242'15.5"W) to 29203'39.5"N 90242'17.6"W
- 11358 47 ed., 02/22/97 LAST LNM 21/97 NAD 83(CGD8) 22/97 LA - BARATARIA BAY AND APPROACHES Delete Platform: "NFE-WD-35-2" 29209'32.0"N 89247'56.0"W
- 11359 7 ed., 07/27/96 LAST LNM 50/95 NAD 83 (CGD8) 22/97 LA - LOOP DEEPWATER PORT - LOUISIANA OFFSHORE OIL PORT Platform: "ZI-GI-82-A" 28243'17.0"N 89257'55.0"W Add
- 11360 37 ed., 12/07/96 LAST LNM 21/97 NAD 83(CGD8) 22/97 FL - CAPE ST. GEORGE TO MISSISSIPPI PASSES - MINERAL LEASE CHART Add Platform: "CH-MP-120-1-CE" 29²27'52.0"N 88²41'09.0"W Platform: "ZI-MP-92-12" 29236'59.0"N 88251'56.0"W
- 11363 34 ed., 08/31/96 LAST LNM 21/97 NAD 83(CGD8) 22/97 LA - CHANDELEUR AND BRETON SOUNDS Platform: "CH-MP-120-1-CE" 29²27'52.0"N 88²41'09.0"W Add

Platform: "ZI-MP-92-12" 29236'59.0"N 88251'56.0"W

11366 3 ed., 10/15/94 LAST LNM 21/97 NAD 83 - METRIC ONLY (CGD8) 22/97

(Temp) LA - MS - APPROACHES TO MISSISSIPPI RIVER

Gulfport Ship Channel Lighted Wreck Buoy "WR2", Q R, red 30208'35.0"N Add 88256'45.0"W

11366 3 ed., 10/15/94 LAST LNM 21/97 NAD 83 - METRIC ONLY (CGD8) 22/97 LA - MS - APPROACHES TO MISSISSIPPI RIVER Delete Platform: "NFE-WD-35-2" 29209'32.0"N 89247'56.0"W

Platform: "CH-MP-120-1-CE" 29²27'52.0"N 88²41'09.0"W Add Platform: "ZI-MP-92-12" 29236'59.0"N 88251'56.0"W

Platform: "ZI-GI-82-A" 28243'17.0"N 89257'55.0"W

Symbol: Dangerous Wreck (PA)" and legend: "awash" (60ft F/V SAN JOSE) (CGD8 088-97) 30²08'15.0"N 88²56'30.0"W

11367 28 ed., 03/29/97 LAST LNM 21/97 NAD 83 (CGD8) 22/97
MS - LA - INTRACOASTAL WATERWAY - WAVELAND TO CATAHOULA BAY
Relocate Lake Borgne Range Front Light (30²08'24.4"N 89²36'39.6"W) to
30²08'24.7"N 89²36'40.0"W

11369 41 ed., 02/03/96 LAST LNM 19/97 NAD 83 (CGD8) 22/97 LA - LAKE PONTCHARTRAIN AND MAUREPAS Change Pass Manchac Daybeacon "4" to Pass Manchac Daybeacon "2", TR on pile 30²17′57.7"N 90²19′28.3"W

Add Pass Manchac South Channel Buoy "3", Green can 30²16'51.1"N 90²18'32.1"W Pass Manchac South Channel Buoy "5", Green can 30²17'12.0"N 90²18'21.7"W Pass Manchac South Channel Light "7", FI G 2.5s, 17ft, 4M 30²17'33.0"N

90²18'11.5"W

11373 37 ed., 03/16/96 LAST LNM 20/97 NAD 83 (CGD8) 22/97 (Temp) AL - MS - LA - MISSISSIPPI SOUND AND APPROACHES - DAUPHIN ISLAND TO CAT ISLAND

Add Gulfport Ship Channel Lighted Wreck Buoy "WR2", Q R, red 30²08'35.0"N 88²56'45.0"W

11373 37 ed., 03/16/96 LAST LNM 20/97 NAD 83 (CGD8) 22/97
AL - MS - LA - MISSISSIPPI SOUND AND APPROACHES - DAUPHIN ISLAND TO CAT ISLAND

Add Symbol: Dangerous Wreck (PA)" and legend: "awash" (60ft F/V SAN JOSE) (CGD8 088-97) 30²08'15.0"N 88²56'30.0"W Ship Island Pass Entrance Passing Light "A", FI G 4s, 10ft, 3M 30²12'09.2"N

89200'00.2"W

Ship Island Pass Entrance Passing Light "B", FI G 4s, 30ft, 3M 30²14'34.2"N

89201'59.5"W

11389 29 ed., 08/28/93 LAST LNM 17/97 NAD 83 (CGD8) 22/97 FL - ST. JOSEPH AND ST. ANDREW BAYS Delete Murray Point Channel Daybeacon "2" 30²01'41.0"N 85²28'36.0"W

11393 18 ed., 08/28/93 LAST LNM 02/97 NAD 83 (CGD8) 22/97 FL - INTRACOASTAL WATERWAY - LAKE WIMICO TO EAST BAY Delete Murray Point Channel Daybeacon "2" 30²01'41.0"N 85²28'36.0"W

DRILL RIGS/VESSELS ESTABLISHED

| LAT. | LON. | BLOCK RIG/VESSELS | CHART | TTYPE | STATU | IS | | | |
|---------------------------|-------------------------|-------------------|--------|---------|---------|-------|-------|-----|-----|
| 28 ² 48'54.0"N | 88 ² 28'07.0 | O"W | MC-162 | 2Americ | a | 11360 | SS | New | |
| 29202'42.0"N | 89 ² 17'12.0 | O"W | SP-11 | Mallard | l 53 | 11361 | BR | New | |
| 28 ² 57'40.0"N | 90 ² 13'31.0 | O"W | ST-27 | Colorad | do | 11357 | JU | New | |
| 28 ² 53'55.0"N | 90230'16.0 | O"W | ST-51 | Hercule | es 20 | 11357 | JU | New | |
| 28 ² 02'52.0"N | 90 ² 31'33.0 | O"W | EB-910 |) Ambas | sador | 11340 | SU | New | |
| 29 ² 02'01.0"N | 91 ² 27'01.0 | O"W | EI-105 | Hercule | es 15 | 11351 | JU | New | |
| 29 ² 03'07.0"N | 91 ² 27'14.0 | O"W | EI-100 | Anchor | age | 11351 | JU | New | |
| 29 ² 24'22.0"N | 91 ² 57'50.0 | O"W | SMI-22 | 4 | Bice | 11349 | JU | New | |
| 29 ² 20'28.0"N | 91 ² 59'43.0 | O"W | SMI-12 | 3 | Louisia | na | 11340 | JU | New |
| 29 ² 17'05.0"N | 92206'22.0 | O"W | SMI-24 | 5 | Pool 54 | ļ | 11349 | JU | New |
| | | | | | | | | | |

| 28 ² 55'50.0"N 92 ² 45'28.0"W | EC-160 Drake | 11340 JU | New | | |
|---|--------------|------------|-------|-----|-----|
| 28 ² 28'37.0"N 93 ² 09'18.0"W | WC-507 | Marine 303 | 11340 | JU | New |
| 28 ² 32'57.0"N 93 ² 11'34.0"W | WC-479 | Phoenix I | 11340 | JU | New |
| 28 ² 23'29.0"N 93 ² 11'55.0"W | WC-528 | Marine 304 | 11340 | JU | New |
| 28 ² 16'51.0"N 93 ² 31'15.0"W | HI-293 Champ | ion 11340 | JU | New | |
| 28 ² 28'07.0"N 93 ² 58'30.0"W | HI-A415 | SeaHawk | 11340 | JU | New |

DRILL RIGS/VESSELS REMOVED

| D1 (122 1 (100) 12002 | | | | | | | |
|---|--------------|----------------|---------|-------|--------|----------|-------|
| LAT. LON. | BLOCK RIG/VI | ESSELS CHAR | TTYPE | STATL | JS | | |
| 29 ² 16'03.0"N 88 ² 19'05.0"N | V | MP-286Louisia | ına | 11360 | JU | Cleared | b |
| 29 ² 01'37.0"N 89 ² 16'46.0" | V | SP-24 Mallard | 1 53 | 11361 | JU | Cleared | b |
| 29 ² 04'32.0"N 89 ² 16'54.0"N | V | SP-11 BSI-5 | 11361 | BR | Unrepo | orted | |
| 28 ² 56'15.0"N 89 ² 45'41.0" | | WD-93 Ensco | | 11358 | JU | Aid Re | mains |
| 29 ² 09'32.0"N 89 ² 47'57.0" | V | WD-35 Marine | 16 | 11358 | | Aid Re | mains |
| 28 ² 57'19.0"N 90 ² 21'18.0"\ | | ST-30 Colora | | 11357 | JU | Unrepo | |
| 28 ² 51'30.0"N 90 ² 28'59.0"\ | | ST-52 Hercule | | 11357 | JU | Cleare | |
| 28 ² 03'12.0"N 90 ² 32'51.0" | | EW-910 | Ambas | | 11340 | SS | |
| Unreported | | | | | | | |
| 28 ² 33'07.0"N 91 ² 13'33.0"\ | V | SS-202 Phoeni | x 1 | 11340 | JU | Aid Re | mains |
| 29 ² 03'48.0"N 91 ² 26'55.0" | | El-100 Anchor | age | 11351 | | Platfori | |
| Remains | | | 3 | | | | |
| 29 ² 59'07.0"N 91 ² 28'50.0" | V | El-119 Hercule | es 15 | 11351 | JU | Unrepo | rted |
| 28 ² 47'45.0"N 91 ² 43'27.0" | | El-175 High Is | | | JU | Cleare | |
| 28 ² 16'27.0"N 92 ² 06'13.0" | | SMI 137 | Ensco | | 11340 | JU | |
| Platform Remains | | | | | | | |
| 28 ² 34'14.0"N 92 ² 26'43.0" | V | VR-245 | Drake | | 11340 | JU | |
| Unreported | | | | | | | |
| LAT. LON. | BLOCK RIG/VI | ESSELS CHAR | TTYPE | STATU | JS | | |
| 28 ² 16'25.0"N 93 ² 19'37.0" | V | WC-549 | Marine | 304 | 11340 | JU | |
| Unreported | | | | | | | |
| 28 ² 26'11.0"N 93 ² 32'44.0"\ | V | WC-497 | Champ | ion | 11340 | JU | |
| Unreported | | | | | | | |
| 29 ² 33'58.0"N 93 ² 38'20.0"\ | V | WC-91 Pool 54 | 4 11341 | JU | Aid Re | mains | |
| 28 ² 29'30.0"N 93 ² 56'59.0" | V | HI-A416 | SeaHa | wk | 11340 | JU | Aid |
| Remains | | | | | | | |
| 29 ² 13'43.0"N 94 ² 27'52.0" | V | HI-154 Amos I | Runner | 11323 | SS | Subsea | a |
| Remains | | | | | | | |
| 26 ² 53'50.0"N 94 ² 54'00.0"N | V | EB-994 Americ | a | 11340 | SS | Cleared | b |
| 28204'05.0"N 96228'24.0"N | V | MI-634 Ensco | 83 | 11300 | JU | Aid Re | mains |
| 27 ² 23'52.0"N 96 ² 55'05.0" | V | MU-847Marine | 303 | 11300 | JU | Unrepo | rted |
| | | | | | | • | |

(5)

ADVANCE NOTICE OF CHANGES TO AIDS TO NAVIGATION

None

(6)

PROPOSED CHANGES TO AIDS TO NAVIGATION

None

(7)

GENERAL INFORMATION

FL - EAST PASS MAIN CHANNEL (DESTIN PASS) - CHOCTAWHATCHEE BAY ENTRANCE - Bridge Information - Repeated for Safety

The low steel of the East Pass Main Channel (Destin Pass) State Road 30/U.S. 98 fixed span bridge has been reported to be approximately one foot less

than shown on charts. Vertical clearance of the bridge has been reported to be 49.15 feet above mean high water.

Mariners are reminded that the west fender system of the bridge has been damaged as a result of an allision, and caution should be exercised when

transiting the bridge.

Charts: 11385, 11388 Ref: CGD8 LNM 20/97

FL - INTRACOASTAL WATERWAY - SANTA ROSA SOUND - Bridge Fender Damaged

The southwest corner of the fender system and clearance gauge on the County Road 399 fixed span highway bridge (Bob Sykes Bridge) across the

Intracoastal Waterway at Mile 189.1, east of Harvey Lock, has been severely damaged. Mariners should exercise extreme caution when transiting the

bridge.

Charts: 11378 Ref: CGD8 BNM 0077-97 OB

MS - GULF OF MEXICO - NOAA Buoy Deployment

NOAA buoy 3DV07/42MRS has been deployed in approximate position 30-05-23.3N 88-46-06.1W in a depth of 46 feet and with a watch circle radius of

approximately 30 yards. The buoy is a 3-meter discus-shaped yellow hull with a 5-meter tripod mast. The buoy is marked with the letter and numbers

"NOAA", "42MRS" and shows a group flashing (4) yellow light every 20 seconds. All vessels are requested to pass well clear.

Charts: 11373

LA - MISSISSIPPI RIVER GULF OUTLET - Seasonal Disestablishment

The sound signal on Mississippi River Gulf Outlet Light "93" (LLNR 10970) has been seasonally disestablished. The horn operates continuously from

approximately November 1 to April 30.

Charts: 11364 Ref: BNM 0629-97 NO

LA - LOWER MISSISSIPPI RIVER - NEW ORLEANS TO BATON ROUGE - Dredging Operations

The dredge OUACHITA is currently working at Medora Crossing, approximately Mile 212.0 above Head of Passes on the Mississippi River. The dredge

WHEELER is also working at Belmont Crossing, approximately Mile 154.0 above Head of Passes on the Mississippi River. Upon completion of these

assignments, the dredges may work the other deep draft crossings from Baton Rouge to New Orleans, Louisiana. The dredges work 24 hours a day, 7

days a week, and will give way to passing navigation.

Charts: 11370 Ref: COE Navigation Bulletin 97-49 NO

LA - INTRACOASTAL WATERWAY - NEW ORLEANS TO PORT ARTHUR - BAYOU BARATARIA - Temporary Change to Bridge Vertical Clearance

Until further notice, the vertical clearance of the fixed span highway bridge (Wagner Bridge) at Crown Point across the Intracoastal Waterway at Mile 11.9,

west of Harvey Lock, has been reduced to 65 feet above high water. Scaffolding, equipment and personnel are suspended from the bridge to make

emergency structural repairs, resulting from a recent allision. The green channel center navigation light is missing, but the scaffolding will marked with

yellow retro-reflective material and lighted with yellow flashing lights as soon as practicable.

Charts: 11365, 11367 Ref: CGD8 BNM 0079-97 OB

TX - CLEAR CREEK - Bridge Removal Operations - Repeated for Safety

Bridge removal operations are underway on the Southern Pacific Railroad Bridge across Clear Creek, Mile 1.0 at Kemah-Seabrook, Texas. Construction

equipment will be on scene until further notice. The swing span has been removed, but the center pier and the east and west ends and dolphin system

remain at this time. Demolition of the substructure of the pivot pier is underway. Mariners should avoid the area on the north side where demolition of the

remaining parts of the bridge is being conducted. The old trestle on the south side of the channel has been removed to the mudline. Although this area

may be transited, depths are unknown. For additional information contact Mr. Gary Hill at 402-280-7099. Notices to mariners will be updated as

information becomes available.

Charts: 11326, 11327 Ref: CGD8 BNM 0062-97 OB TX - CLEAR CREEK CHANNEL - Seasonal Disestablishment

The sound signal on Clear Creek Channel Light "2" (LLNR 25070) has been seasonally disestablished. The horn operates continuously from

approximately November 1 to April 30.

Charts: 11326, 11327

TX - INTRACOASTAL WATERWAY - STOVER POINT TO BROWNSVILLE - Bridge Maintenance

Maintenance operations are underway on the Queen Isabella Causeway Bridge across the Intracoastal Waterway, Mile 665.4, near Port Isabel, Texas.

Work will be accomplished from a 20-foot by 20-foot barge which will be anchored under the causeway. Work will be done during daylight hours. The

project is expected to continue through July 7, 1997.

Charts: 11302 Ref: BNM 0253-97 CC

REGATTAS/FIREWORKS

Waterway Date/Time Event Sponsored By Unit or Patroled

Biloxi Bay June 14-15, 1997 Chapman Regatta Ocean Springs Yacht No

Biloxi, Ms 11:00 a.m.- 3:00 p.m. Club

Mississippi Sound June 20-22, 1997 GYA Offshore Challenge Gulfport Yacht Club

No

Gulfport, MS 12:00 p.m.- 4:00 p.m. Cup

Mississippi River June 24, 1997 The Great Steamboat Delta Queen Steamboat

USCGC Point Sal

New Orleans, La 4:30 p.m.- 5:30 p.m. Race Company

Gulf of Mexico June 27-28, 1997 Gulfport-Pensacola Southern Yacht Club No

Gulfport to Pensacola 12:00 p.m.- 11:00 p.m. Boat Race

(8)

CORRECTIONS TO LIGHT LIST, VOLUME IV, GULF OF MEXICO, 1996

(1) (2) N/W (3) (4)(5)(6) (7)(8)No. Rng Name and Location Position Characteristic Ht Structure Remarks

(22/97)

8506 SHIP ISLAND PASS 30 12.1 FI G 4s 10 3 On platform.

ENTRANCE PASSING 89 00.0 LIGHT A

* * * * * * *

8506.1 SHIP ISLAND PASS 30 14.6 FI G 4s 30 3 On platform.

ENTRANCE PASSING 89 02.0

LIGHT B

* * * * * * * * * (22/97)

10400 Pass Manchac Daybeacon 2 30 18.0 TR on pile. 90 19.5

00 .0.0

(22/97)

| 10412 * | - Buoy 3 | * | * | * | * | Green * | can. | (22/97) |) |
|------------|---|--------------------|---------------|-------|--------------|------------------|-----------|--------------------|---|
| 10417 * | - Buoy 5 | * | * | * | * | Green * | can. | (22/97) |) |
| | - LIGHT 7 18.2 | 30 17. | 5 FI G 2 | .5s | 17 | 4 | SG on | pile. | |
| * | * * | * | * | * | * | * | | (22/97) |) |
| | *Change Head *Marina Del So - LIGHT 1 02.9 | ol Chann | | s 16 | | SG on | pile. | Private (22/97) | |
| | - LIGHT 11 02.9 | 29 33. | 1 FI G 2 | .5s | 12 | | SG on | pile. | Private aid. |
| | - LIGHT 12 02.9 | 29 33. | 2 FI G 2 | .5s | 12 | | TR on | | Private aid. |
| | * | * | * | | | | | (22/97) |) |
| • | 29505(22/97) | | | | | | | | |
| (1) No. | (2) Name and Loc Remarks | N/W(ation | 3) Positio | on | (4) Chara | (5) cteristic | (6) Ht | (7) Rng | (8) Structure |
| 33030 | - RANGE REA Visible 2 ² each | | Т | Iso W | / 6s | 62 | | KRW-I | on skeleton tower |
| ho | 3,037 yards, from front lig rizon. | 261.1 ² | | FI W | 4s 20 | 3 | on pla | atform o Passin | n piles. rangeline. g light visible around |
| • | (22/97) | | | | | | | | |
| (9) | | | | | | | | | |

ENCLOSURES

(1) Mississippi River Deep Draft Crossings